Downloading files from DOS

You can use the DOS **COPY** command to download PostScript files to the printer.

1. Locate the files you want to use on the Windows 3.1 Driver and Printer Utilities diskette. You can copy the files to your computer's hard disk, or use the files directly from the diskette.

2. Use the DOS **COPY** command to send the desired file to the printer. For example, to reset the printer you would send the *RESET.PS* file to the printer.

- If your printer is connected to the parallel (LPT) port, type the following command (where *x* is 1, 2, or 3):

  COPY RESET.PS LPT*x*:

- If your printer is connected to the optional serial (COM) port, type the following command (where *x* is 1, 2, or 3):

  COPY RESET.PS COM*x*:

- If your printer is connected to an optional Novell or TCP/IP network, you should follow the instructions provided with your network software.