Printing the PANTONE Color chart

Note *Do not use any color corrections in a driver, or with a downloadable utility file, or from the printer's front panel, when printing the PANTONE Color chart or when printing PANTONE Colors from an application. Using color corrections causes the PANTONE Colors to print incorrectly.*

The *PANTONE-Tek Phaser 540* (*PANT540.PS*) file prints a PANTONE Color sampler chart (about 46 pages in length). Use the chart to select colors within an application that allows you to specify PANTONE Colors.

Use the following links to obtain directions on printing color charts using TekColor color corrections:

Directions for Macintosh

Directions for PC/Workstations

Macintosh users

1. Decompress the *Phaser 540 Samplers.sea* and the
    Phaser 540 Utilities.sea file from the Macintosh Driver and Printer
    Utilities diskette onto your hard disk.

2. Select the appropriate printer in the **Chooser**.

3. Select the **None** option in the TekColor Corrections menu on the
    printer's front panel, or send the *No Color Correction* utility file to
    the printer.

4. To print the chart, use the *LaserWriter Utility* to download the
    PANTONE-Tek Phaser 540 file to the printer.

5. Select PANTONE Colors within an application using the colors on
    the chart.

6. Print your document using one of the following methods:

    ■   **If you are printing from a Tektronix driver:** Print your document
        with the **None** option selected. Any other color correction selection
        in the driver causes the PANTONE Colors to print differently.

    ■   **If you are not using a Tektronix driver:** Print your document with
        the **None** option selected in the TekColor Corrections menu on the
        printer's front panel, or send the *No Color Correction* utility file to
        the printer.

PC and workstation users

1. Copy the *PANT540.PS* sampler file from the *SAMPLERS* directory on the Tektronix Windows 3.1 Driver and Printer Utilities diskette onto your computer's hard disk. You may want to place this file in a *Utilities* directory. Or, you can download this file directly from the diskette.

2. Select the **None** option in the TekColor Corrections menu on the printer's front panel, or send the *NOCORECT.PS* file to the printer.

3. Use one of the following methods to print the PANTONE Color chart:

   - **PC users:** Use the DOS **COPY** command or the **Copy** command in Windows **File Manager** to send the *PANT540.PS* sampler file to the printer.

   - **Workstation users:** Send the *PANT540.PS* file to the printer as you would any PostScript file.

4. Select PANTONE Colors within an application using the colors on the chart.

5. Print your document using one of the following methods:

   - **If you are printing from a Tektronix driver:** Print your document with the **None** option selected. Any other color correction selection in the driver causes the PANTONE Colors to print differently.

   - **If you are not using a Tektronix driver:** Print your document with the **None** option selected in the TekColor Corrections menu on the printer's front panel, or send the *NOCORECT.PS* utility file to the printer.