


Downloading files from Windows 3.1

You can use the **Copy** command in the Windows **File Manager** to download PostScript files to the printer.

1. Locate the directory containing the printer's utility files. This directory was created when you ran the installer application.
2. Select the utility file you want to send to the printer, for example *RESET.PS*.
3. From the **File** menu, select **Copy**. The **Copy** dialog box appears with the utility file you selected listed in the **From** field:



4. In the **To** field, type the port your printer is connected to. For example, type **LPT1:** for a parallel port connection, then click **OK**.
5. If the **Confirm File Replace** dialog box appears, click **Yes** to continue; the file is downloaded to the printer.