

Downloading files from DOS

You can use the DOS **COPY** command to download PostScript files to the printer.

Use the DOS **COPY** command to send the desired file to the printer. For example, to reset the printer you would send the *RESET.PS* file to the printer.

- If your printer is connected to the parallel (LPT) port, type the following command (where *x* is 1, 2, or 3):

COPY RESET.PS LPTx:

- If your printer is connected to the optional serial (COM) port, type the following command (where *x* is 1, 2, or 3):

COPY RESET.PS COMx:

- If your printer is connected to an optional Novell or TCP/IP network, you should follow the instructions provided with your network software.